| ECS Configuration Change Request | • | F | Page 1 of 1 | Pages |
|--|---|---|------------------|---------------|
| CCR No. 98-0678 Logged Date 6-5-98 | Rev | Request T | ype CCR | |
| Priority Routine Urgent X Emergency | Affected Release | B.0 | Change Class | s II |
| Title (description) G0ais05 in C101P is to be moved to C101. | | | | |
| Documents Affected GDAAC Physical Floor Plan - 920-726-004-66409 Cable Management Plan (No Change) - 920-726-005- | Source Nos (RID, N Reference REVOY None. | ICR, Action Ite | em, GSFC CCR, | etc.) or Tech |
| RTM Change Start New Baseline | | | | |
| Problem G0ais05 (EIN:0678) needs to be relocated from C101P to C101. Global Comm. Data Corp.(GCDC) has been assigned to C101P. | | | | |
| Proposed Solution Move G0aix05 to C101. NEED DATE: 6/10/98 | | | | |
| Impact Analysis: | | | | |
| 1 • | Rel. B x Sys. Eng | FOS Rel. C Sys Verf Acpt | M&G SCDO Arch | |
| Cost: None x Small (Not exceeding \$100,000) | Medium (\$100,000 to \$500,000) | Large (Over \$500,000) | | |
| Schedule: None X Other | | *************************************** | | |
| Additional LOC N/A | Man-Month | s <u>N/A</u> | | |
| Materials N/A | | | | |
| Originator Eric Obligacion GDAAC Local Maintenance Coordinator Signature Office Mark Fuerst Office Manager Authority | | | G / 3 / Date | 197) - |
| GDAAC M&O Manager Signature | | | Date | |
| Disposition Approved Approved w/Comm | | | Disapproved | ı 🗀 |
| Comments: This is not | the better | way | h de | they. |
| CCB Chairperson Signature | I facker | | 6/5/ | 98 ate |
| CM01OC96 | , | | - | ECS |
| Jino i Jour | | | | |

ORIGINAL